

Cour Surveyor's Record, Tillamook Cour Oregon

239

T 3 S, R 10 W

Rewitnessed corners. Mervin Whitmore, U.S. Forest Service

~~XXXXX~~

Sec. Cor

$\frac{9}{10}$   
 $\frac{16}{15}$

Point for corner determined by reference to the record, bearing and distance to two of the original bearing trees.  
At point for corner set a 3/4" iron pipe from which  
A hemlock stump badly decayed with scribe marks visible but not legible bears S 75°W 79 lks. (old BT)  
A fallen hemlock with scribe marks on underside bears N 59°W 34 lks.  
A 7" fir bears N 44°W 34 feet dist. mkd. T3SR10WS9BT (new BT)  
A 8" fir bears N 55°E 10 1/2 feet dist mkd. T3SR10WS10BT (new BT)  
A 6" fir bears S 14°E 24 1/2 feet dist mkd. T3S R10WS15BT (new BT)  
A 10" spruce bears S 34°W 25 1/2 feet fist mkd. T3SR10WS16BT (new BT)  
This corner sets 24 feet east of a spring branch course south.

Marked in the presence of Marvin Thomason & E. Wayne Bronson,  
June 11, 1954.