

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 1, 2, 11 and 12,  
T. 2 N., R. 8 W., W.M., Tillamook County, Oregon.

ORIGINAL

Stone 15" x 10" x 8" (found in place, 5 notches on S side,  
1 notch on E side) from which a:

- 48" Hemlock bears N44°E 63 lks.; now missing, point falls in slide area.
- 40" Hemlock bears S50°E 25 lks.; now missing, point falls in slide area.
- 16" Hemlock bears S34°W 30 lks.; roots remaining.
- 7" Hemlock bears N26°W 27 lks.; now 30" snag, part of scribe T remaining on lower face.

RESTORED

Var. 21½°

Erected mound of rock around corner stone, from which a:

- 60" Fir stump bears S54½°E 65.4 ft.; scribed T2N R8W S12 BT.
- 66" Fir stump bears N71°E 62.2 ft.; scribed T2N R8W S1 BT.
- 46" Fir stump bears N12½°W 80.4 ft.; scribed T2N R8W S2 BT  
RE 2311
- 72" Fir snag bears S65°W 89.5 ft.; scribed T2N R8W S11 BT.


Set 4" x 4" x 72" white painted Cedar post 2 ft. SW of corner stone.

Oregon State Board of Forestry metal location poster on 60" fir stump BT.

Also poster on 4" x 4" x 72" white painted Cedar post 300 ft. N. on S edge logging road.

Dated September 1, 1955.

Restored by Richard A. Morris under my direction.  
Richard A. Morris, Engr. Aide.



Present and witnessed by Robert Sturm  
Forest Logan  
Lloyd Geraths