

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 2, 3, 10 and 11, T. 1S., R. 7W., W.M., Tillamook County, Oregon.

ORIGINAL

Post now missing, from which a:

- 8" Hemlock bears N27½°E 3 lks.; now 12" down rotted stub, scribes T1S R7W S2 BT remaining, roots in place next to 38" Fir stump.
- 8" Hemlock bears N27°W 51 lks.; now 12" down, out of place, scribes T1S, R7W BT remaining.
- 6" Hemlock bears S74½°W 46 lks.; missing.
- 6" Hemlock bears S63½°E 47 lks.; missing.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T 1S R7W S2 S3 S10 S11 1955 RE 2311," 33 inches in ground, and from which a:

- 45" Fir stump bears S4°W 24.7 ft.; scribed T1S R7W S10 BT.
- 34" x 15" Fir stub bears N17°W 60.0 ft.; scribed T1S R7W S3 BT RE 2311.
- 31" Fir snag bears S51°E 86.5 ft.; scribed T1S R7W S11 BT.
- 38" Fir stump bears N41°E 3.6 ft.; scribed T1S R7W S2 BT.

Set 4"x4"x72" white painted Cedar post 1.5 ft. NW of pipe.

Oregon State Board of Forestry metal location poster on 38" Fir stump BT.

Also poster on 60" Fir snag S62½°W 28.4.

Also poster on 4"x4"x72" white painted Cedar post on W edge cat road 155.5 ft. East.

Dated September 28, 1955.

Restored by Arnold G. Gibson under my direction.
Arnold G. Gibson, Ass't. Eng.



Present and witnessed by Lloyd Geraths