

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Closing corner common to Sections 19 and 30, T3N,
R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 54" Fir bears N55 3/4°E 64 lks.; now 48" stump, scribes T3N, R6W S19 C BT remaining.
- 40" Hemlock bears S23 1/4°E 45 lks.; now 32" stump, bottom of original face remaining.
- 40" Hemlock bears S62°W 17.5 lks.; just roots and root hole remaining.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N S24 S19 S30 CC R6W 1955 RE2311," 33 inches in ground, and from which a:

26" Fir stump bears S37°E 112.1 ft.; scribed T3N R6W S30 CC BT RE2311.

Set 4" x 4" x 72" white painted Cedar post 2 ft. W of pipe. Oregon State Board of Forestry metal location poster on original 54" BT.

Dated September 19, 1955.

Restored by Richard A. Morris under my direction.
Richard A Morris, Engr. Aide



Present and witnessed by Lloyd Geraths
Robert Sturm
Forrest Logan