

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 24 and 25 (East side)  
T3N, R7W, W.M., Tillamook County, Oregon

ORIGINAL

Post, now missing, from which a:

- 24" Hemlock bears N64°E 69 lks.; marks reported destroyed by resurvey of 1893, roots remaining.
- 20" Hemlock bears S53°E 78 lks.; marks reported destroyed by resurvey of 1893, roots remaining.
- 16" Hemlock bears S68°W 48 lks.; now 18" uproot, original axe marks remaining, roots in place.
- 60" Fir bears N79°W 65 lks.; now 55" stump, portion of scribe on upper face and BT remaining on lower face.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N S24 S25 R7W T3N R6W S30 1955 RE2311," 33 inches in ground, in mound of stone, and from which a:

- 34" Fir stump bears S34°W 103.2 ft.; scribed T3N R7W S25 BT.
- 11" Noble Fir bears N63°W 149.4 ft.; scribed T3N R7W S24 BT RE2311.

Set 4" x 4" x 72" white painted Cedar post 1.5 ft. NW of pipe. Oregon State Board of Forestry metal location poster on 11" Fir N19½°E 95.0 ft. (on North edge road).

Dated September 19, 1955.

Restored by Richard A. Morris under my direction.  
Richard A. Morris, Engr. Aide



Present and witnessed by Forrest Logan  
Lloyd Geraths  
Robert Sturm