

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 1, 2, 11 and 12,  
T. 1S., R. 7W., W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 16" Hemlock bears N63°E 28 lks.; now 24" root stub 1' high, scribes and face missing.
- 30" Fir bears S71½°E 91 lks.; now 37" stump, scribes BT visible, upper face cut off when logged.
- 40" Hemlock bears S14°W 58 lks.; now 48" stump, edges of old burnt out face visible, scribes burnt off.
- 6" Hemlock bears N40½°W 66 lks.; now missing, just roots in place.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R7W S2 S1 S11 S12 1955 RE 2311," 24 inches in ground, in mound of stone, and from which a:

- 40" Fir stump bears N2°W 29.5 ft.; scribed T1S R7W S2 BT RE 2311.
- 60" Fir stump bears N53°E 40.0 ft.; scribed T1S R7W S1 BT.
- 34" Fir stump bears S58°W 4.5 ft.; scribed T1S R7W S11 BT.
- 36" Fir stump bears S20°E 39.6 ft.; scribed T1S R7W S12 BT.

Set 4"x4"x72" white painted Cedar post, 2' SE of pipe.  
Oregon State Board of Forestry metal location poster on 34" Fir stump BT.

Also poster on 4"x4"x72" white painted Cedar post approx. 230 ft. E. on W. edge Hembre Ridge Road.

Dated September 20, 1955.

Restored by Richard A. Morris under my direction.  
Richard A. Morris, C.E. I



Present and witnessed by Lloyd Geraths  
Forrest Logan  
Robert Sturm