

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 7, 8, 17 & 18,
T2N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 18" Hemlock bears N18°W 26 lks.; now missing, position falls in slide area.
- 4" V. Maple bears N22°E 24 lks.; now missing.
- 13" Hemlock bears S43°E 72 lks.; position now covered by logs.
- 16" Spruce bears S45°W 44 lks.; now 36" stub 10" high, scribes T2N R9W S visible, rest unexposed.

RESTORED


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R9W S7 S8 S18 S17 1956 RS 359," 34 inches in ground, and from which a:

- 6" Spruce bears S1°W 16.7 ft.; scribed T2N R9W S18 BT RS 359.
- 34" Alder bears N58°W 36.9 ft.; scribed T2N R9W S7 BT (bark scribed)
- 18" Alder bears S74°E 43.8 ft.; scribed T2N R9W S17 BT (bark scribed)
- 12" Fir bears N25½°E 121.7 ft.; scribed T2N R9W S8 BT.

Oregon State Board of Forestry metal location poster on 6" Spruce BT.
Set 4" x 4" x 72" white painted Cedar post lft. NE of pipe.

Dated September 4, 1956.

Restored by Richard Morris under my direction.
Richard Morris, Transitman



Present and witnessed by L. Geraths

Book I