

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 15, 16, 21 and 22,
Township 2 South, Range 8 West, W.M., Tillamook, County, Oregon.

ORIGINAL

Stone, 16" x 8" x 8" (now missing) from which a:

- 10" Hemlock bears N27°E 83 lks.; now 20" stump,
scribes & face cut off when logged.
- 5" Hemlock bears N79°W 48 lks.; now missing, position
falls in slide area.
- 6" Hemlock bears S71°E 37 lks.; now down, scribes R8W S22 visible.
- 6" Hemlock bears S39°W 47 lks.; now missing.

RESTORED by Louis Amort RE 2311, August 15, 1952

1 1/2" x 36" galvanized iron pipe with 3" bronze cap (now missing,
point falls in slide area) from which a:

- 36" Cedar stub bears N62°W 45.3 ft.; now uprooted down hill
out of place, scribes T2S R8W S16 BT RE 2311 visible, roots
left in place.
- 66" Cedar snag bears N55 1/2°E 70.4 ft.; now 66" stump with
scribes T2S R8W S15 BT visible, and OSBF yellow
location poster.

RESTORED

Var. 21 1/2°E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY T2S R8W S16 S15 S21 S22
1956 RS 359," 35 inches in ground, in mound of stone,
and from which a:



65" Cedar stump bears N57°W 98.9 ft.; scribed T2S R8W
S16 BT RS 359.

Oregon State Board of Forestry metal location poster on 65"
Cedar stump BT.

Set 4"x4"x72" white painted Cedar post 1.5 ft. SW of pipe.

Dated July 31, 1956

Restored by Richard A. Morris under my direction.
Richard A. Morris, Transitman



Present and witnessed by Lloyd Geraths
Robert Sturm