

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 18 and 19, T. 1S, R. 6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 10" Hemlock bears S. 53° W. 9 lks.; log laying over this point.
- 8" Hemlock bears N. 51° E. 42 lks.; now 25" stub 10" high, 1/SB visible, rest burnt off.

RESTORED

Var. 21-1/2 E.

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S18 S19 1956 RS359," 34 inches in ground, and from which a:



- 69" Fir stump bears N. 17° W. 61.2 ft.; scribed 1/4 S18 BT.
- 36" Fir stump bears S. 16° W. 17.0 ft.; scribed 1/4 S19 BT RS359.

Oregon State Board of Forestry metal location poster on 36" Fir stump BT.

Set 4 x 4 x 72" white painted Cedar post 1.5' N.W. of pipe.

Dated May 14, 1956

Restored by Richard Morris under my direction
Richard Morris, Transitman



Present and witnessed by Lloyd Geraths
Robert Sturm