CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 29 and 30 T3S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL)

Post (now missing) from which a:

4" Cherry bears N40°E 5 lks.; now missing. 4" Cherry bears N22°W 16 lks.; now missing.

RESTORED by W. E. Anderson June 30, 1949.

Found rock and $\frac{1}{2}$ iron pipe (now in place, no marks on rock) from which a:

26" Fir bears S382°E 29.0 ft.; now 28", upper and lower faces grown over. Found old BT dead snag 36° $\frac{1}{4}$ BT; now 46° Snag scribes $\frac{1}{4}$ S

BT visible, bears N3°W 19.2 ft.

RESTORED

'Var. 215°E

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S30 S29 1957 RS 359," 33 inches in ground over above ½" iron pipe, in mound of stone, and from which a:

19" Spruce bears N77°W 47.1 ft.; scribed $\frac{1}{4}$ S30 BT RS 359. Original 28" Fir bears S382°E 29.0 ft.; scribed BT.

Oregon State Board of Forestry metal location poster on 19" Spruce BT. Set 4"x4"x60" white painted Cedar post 2 ft. NE of pipe.

Dated February 21, 1957.

Restored by under my direction. Richard Morris, Transitman

> REGISTERED OREGON LAND SURVEYOR

> > ARNOLD G. GIBSON 359

Present and witnessed by Lloyd Geraths Robert Sturm

Book I

288