

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 13, 14, 23 and 24, T. 2N., R. 8W., W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 19" x 15" x 9" (now in place with 3 notches on S. and 1 on E. faces) from which a:

6" Alder bears N74°E 38 lks.; now missing, position falls in cat road.

5" Alder bears S63°E 42 lks.; now missing, position falls in cat road.

10" Alder bears S26°W 8 lks.; now missing.

8" Alder bears N59°W 22 lks.; now 19" Hem. stub 8' high (bears N40°W 20.4') with scribes T2N R8W S14 visible, lower face unexposed.

RESTORED

Var. 21½°E.

Erected mound of stone around original cornerstone from which a:

69" Fir stump bears N1½°E 72.8 ft.; scribed T2N R8 W S13 BT RS401

48" Fir stump bears N61½°W 67.2 ft.; scribed T2N R8W S14 BT

60" Fir stump bears S80°W 96.2 ft.; scribed T2N R8W S23 BT.

3" Alder bears S21°E 36.5 ft.; scribed in bark, XBT

Oregon State Board of Forestry metal location poster on 48" Fir stump Bt.


Set 4" x 4" x 60" white painted cedar post 1.0' N.W.

Dated September 4, 1957.

Restored by



Richard A. Morris



Present and witnessed by Robert Sturm
Harold Russell.