

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 16 and 17,
T. 1S, R. 7W, W.M., Tillamook County, Oregon

ORIGINAL

Post (missing) from which a:

24" Hemlock bears N78°E 53 lks.; now 28" snag, scribes 1/4 s visible, lower face unexposed.

30" Hemlock bears N28°W 10 lks.; now 36" uproot, roots and root hole in place, scribes 1/4 s BT visible.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S17 S16 1957 RS401," 33 inches in ground, in mound of stone, and from which a:

60" Fir stump bears N 28½°E 32.3 ft.; scribed 1/4 S16 BT RS401.

49" Fir stump bears S45°W 119.4 ft.; scribed 1/4 S17 BT.

20" x 20" x 20" rock mound bears S78°W 110.0 ft.


Oregon State Board of Forestry metal location poster on 60" Fir stump BT. Set 4" x 4" x 60" white Cedar post 2.0' SW of pipe.

Dated October 25, 1957

Restored by



Richard A. Morris



Present and witnessed by Robert Sturm
Harold Russell