

County Surveyor's Record, Tillamook County Oregon

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-Quarter corner common to Sections 31 and 6,
T. 3 & 4N, R. 9W, W.M., Clatsop & Tillamook
Counties, Oregon.

ORIGINAL

Post, (now missing, found $\frac{1}{2}$ " I.P. 2" above ground in fence line w/4" x 4" x 40"
Cedar post 1.0 ft. W on Section line, marked as follows: "1/4 cor" E face;
"S6" S face; "S31" N face; by C-Z crew 1950) from which a:

6" Vinemaple bears S 45°E 2 lks.; missing.

6" Vinemaple bears N58°E 30 lks.; missing.

RESTORATION by unknown persons (Recorded at Clatsop Co. Courthouse).

At the Standard 1/4 corner on the South line of Sec. 31 T4N R9W W.M. I set a
2" x 4" scribed Cedar post and also scribed the following B.T.'s:

10" Douglas Fir bears S20W 24.5 ft.; missing.

14" Douglas Fir bears N61°E 30.7 ft.; missing.

RESTORATION: C-Z survey party, N. Seethoff, E. Bates, 1950.

Finding no BT's re-set said corner from East & West section corners.

RESTORED

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S31 S6 1958 RE2311," 26 inches in ground, over
old pipe, in mound of stone, and from which a:

39" Spruce bears S11° 15'E 193.6 ft.; scribed 1/4 S6 BT.

22" Spruce bears N46°W 240.8 ft.; scribed 1/4 S31 BT RE2311.

Oregon State Board of Forestry metal location poster on 39" Spruce BT.
Corner is approximately 60.0 ft. West of the S.W. corner of a 20' x
40' machine shed with concrete foundation on the Barbour Dairy farm,
on N side of lane.

Dated May 28, 1958

Restored by *R. W. Ross* under my direction.
R. W. Ross, Transitman



Present and witnessed by J. F. Martin
Rob't. Fryor

Book I