

County Surveyor's Record, Tillamook County Oregon

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 22 and 27 (East end) T. 2S, R. 9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 20" Hemlock bears N17W 14 lks.; now 30" stump, scribes T2S R9W S22 visible, lower face unexposed.
- 24" Hemlock bears S52W 23 lks.; now missing, point falls in old skid road.

RESTORED

Var. 21½E


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R9W S22 S27 S23 1958 RS401", 33 inches in ground, and from which a:

- 6" Hemlock bears S14W 24.9 ft.; scribed T2S R9W S27 BT.
- 13" Hemlock bears N75½W 38.6 ft.; scribed T2S R9W S22 BT RS401.

Oregon State Board of Forestry metal location poster on 6" Hemlock BT.  
Set 4" x 4" x 60" white painted Cedar post 1.0' S.W. of pipe.

Dated June 23, 1958

Restored by



Present and witnessed by Robert Sturm  
Harold Russell  
Lloyd Geraths