

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 3, 4, 9 and 10,
T3N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 20" x 9" x 4" (now in place) from which a:

72" Fir bears S7W 20 lks.; now 80" stump, lower face unexposed, upper
face cut off when logged.

16" Hemlock bears N33W 50 lks.; now missing.

(Other original bearing Trees reported missing in 1956)

RESTORATION May 14, 1956 by A. Gibson

7" Fir bears N42W 19.6 ft.; now 10" uproot, roots in place, scribes
visible.

10" Fir bears N51E 66.8 ft.; now 12" uproot laying face down, roots
in place.

15" Cedar bears S17E 63.7 ft.; now missing, point falls in skid road.

RESTORED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON
STATE BOARD OF FORESTRY T3N R8W S4 S3 S9 S10 1959 RS401", 33 inches
in ground at the point for corner with original stone on the East
edge of pipe, and from which a:

8" Fir bears S57W 53.3 ft.; scribed T3N R8W S9 BT.

24" Hemlock bears S88E 125.9 ft.; scribed T3N R8W S10 BT RS401.


Oregon State Board of Forestry metal location poster on 8" Fir BT.

Set 4" x 4" x 66" white painted Cedar post 1.0' S.E. of pipe.

Also poster on 10" Fir B.T. uproot.

Dated June 3, 1959

Restored by



Richard A. Morris
MAY 10, 1957
Richard A. Morris
401

Present and witnessed by W. Peterson

Book I

367

367

367