

CHAINS

REESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY
(See official plat)

One Quarter corner common to Sections 27 and 34, T2S,
R9W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

REESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S27 S34 1959 RS401", 32 inches in ground, and
from which a:

- 16" Cedar bears N9W 23.7 ft.; scribed 1/4 S27 BT RS401.
- 3/4" Hemlock bears S50W 21.2 ft.; scribed 1/4 S34 BT.

Oregon State Board of Forestry metal location poster on 16" Cedar BT.
Set 4" x 4" x 56" white painted Cedar post 1.2' N.W. of pipe.

One Quarter corner common to Sections 27 and 28,
T2S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

REESTABLISHED

Var. 21 1/2 E


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S28 S27 1959 RS401", 34 inches in ground, and
from which a:

- 13" Fir bears N74E 18.6 ft.; scribed 1/4 S27 BT RS401.
- 7" Fir bears N88W 25.5 ft.; scribed 1/4 S28 BT.


Oregon State Board of Forestry metal location poster on 6" Fir N24W 4.6'
Set 4" x 4" x 56" white painted Cedar post 1.1' S.E. of pipe.

April 14, 1959

Reestablished by



Richard A. Morris



Present and witnessed by H. Russell
R. Cop