

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 4 and 9,
T1S, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 24" Hemlock bears N78W 44 lks.; now 33" stump, with scribes BT on log alongside.
- 20" Hemlock bears S6W 45 lks.; now 26" stump, scribes 1/4 S visible, rest unexposed.

RESTORED

Var. 21 1/2 E


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S4 S9 1959 RS401", 34 inches in ground, in small mound of stone, and from which a:

- 60" Fir stump bears S50E 64.9 ft.; scribed 1/4 S9 BT RS401.
- 66" Fir stump bears N20 1/2 E 33.1 ft.; scribed 1/4 S4 BT.


Oregon State Board of Forestry metal location poster on 60" ^{Fir} stump BT.
Set 4" x 4" x 48" white painted Cedar post 1.4 feet N. E. of pipe.

Dated August 4, 1959

Restored by Harold J. Russell under my direction.
Harold Russell, Eng. Tech. I



Richard A. Morris



Present and witnessed by R. Cop
E. Nylund
D. Jones