

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 29, 30, 31 & 32, T1N, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 20" Hemlock bears N41W 42 lks.; now 22" uproot, roots in place, scribes BT visible, rest rotted away.
- 22" Hemlock bears N53E 50 lks.; now 42" stub, face & scribes burnt away.
- 31" Hemlock bears S39E 13 lks.; now 47" stub, face & scribes burnt away.
- 19" Hemlock bears S42W 60 lks.; now missing, root hole in place.

RESTORED

Var. 21 $\frac{1}{2}$ E


Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R7W S30 S29 S31 S32 1959 RS401", 34 inches in ground, in small mound of stone, and from which a:

- 48" Fir stump bears S60 $\frac{1}{2}$ W 25.8 ft.; scribed T1N R7W S31 BT RS401.
- 30" Fir snag bears N64W 94.6 ft.; scribed T1N R7W S30 BT.
- 24" Fir snag bears S8E 28.1 ft.; scribed T1N R7W S32 BT.
- 8" Alder bears N32E 53.2 ft.; scribed in bark, T1N R7W S29 BT.


Oregon State Board of Forestry metal location poster on 24" Fir snag BT.  
Set 4" x 4" x 60" white painted Cedar post 1.2 feet S.W. of pipe.

Dated August 4, 1959

Restored by Harold J. Russell under my direction.  
Harold Russell, Eng. Tech. I



*Richard A. Morris*



Present and witnessed by E. Nylund  
D. Jones