

CHAINS

REESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY  
(See official plat)

One Quarter corner common to Sections 11 and 14, T2S,  
R10W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

REESTABLISHED

Var. 21½E

At a point 792.0'E and 1320.0'S of scribed spruce limb set by County  
Surveyor on July 2, 1912, set 1½" x 36" galvanized iron pipe with 3"  
bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S11 S14 1960  
RS401", 33 inches in ground, and from which a:

31" Spruce bears S41 3/4E 67.5 ft.; scribed 1/4 S 14 BT.  
13" Hemlock bears S27W 162.3 ft.; scribed 1/4 S14 BT RS401.

Oregon State Board of Forestry metal location poster on 13" Hemlock BT.  
Set 4" x 4" x 52" white painted Cedar post 1.0' N.E. of pipe.  
Corner pipe sets in N.W. edge of ditch line that comes from the  
South and drains East.

Present and witnessed by H. Russell, G. Nylund, G. Johnston

Section corner common to Sections 10, 11, 14 and 15,  
T2S, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

REESTABLISHED by double proportionate measurement

Var. 21½E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE  
BOARD OF FORESTRY T2S R10W S10 S11 S15 S14 1960 RS401", 32 inches in  
ground, and from which a:


41" Spruce bears N67W 39.1 ft.; scribed T2S R10W S10 BT RS401.  
44" Cedar bears S32E 49.8 ft.; scribed T2S R10W S14 BT.  
18" Hemlock bears S14½W 31.6 ft.; scribed T2S R10W S15 BT.  
12" Spruce bears N42½E 41.7 ft.; scribed T2S R10W S11 BT.

Oregon State Board of Forestry metal location poster on 18" Hemlock BT.  
Set 4" x 4" x 52" white painted Cedar post 1.0' N.E. of pipe.

Present and witnessed by G. Johnston, H. Russell, R. Cop, G. Nylund, J. Sehorn

Dated August 19, 1960

Reestablished by



*Richard A. Morris*  
MAY 10, 1957  
Richard A. Morris  
401