

*1/4 Sec 25 S 29*

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One Quarter corner common to Sections 25 and 36, T2S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 20" Hemlock bears S43°30'E 15 lks.; now 22" stump, scribes 1/4 S exposed.
- 24" Hemlock bears N12°30'E 12 lks.; now 27" stump, no face remaining, chopped out "E" cruiser mark.

RESTORED

Var. 21½E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S25 S36 1962 RS401", 32 inches in ground, in mound of stone, and from which a:


- 27" Fir bears N74½°E 178.1 ft.; scribed 1/4 S25 BT RS401.
- 72" Fir stump bears S85½°E 144.4 ft.; scribed 1/4 S36 BT.

Oregon State Forestry Department metal location poster on original 20" BT. Set 4" x 4" x 56" white painted Cedar post 2 ft. southwest of corner pipe.

Dated December 14, 1962

Restored by *Billy E. Davis* under my direction.  
 Billy E. Davis, Transitman

Present and witnessed by A. Duncan



*477*