

S.W. 1/4  
27-2-N-6

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 27, 28, 33 and 34, T.2N,  
R.6W, W.M., Tillamook County, Oregon

ORIGINAL

Post (now missing) from which a:

- 12" Hemlock bears N69E 32 lks.; now uprooted, roots in place, grown over axe work unexposed.
- 12" Hemlock bears S21E 39 lks.; now missing.
- 36" Fir bears S52 1/2 W 40 lks.; now 36" uproot, roots and root hole in place, uprooted face down.
- 18" Hemlock bears N19W 38 lks.; now 14" stub 8' high, face and scribes burnt away.

RESTORATION by J. K. Scott, Res. Engineer O.S.H.D. August 19, 1942.

Set 5" x 2 1/2" I.P. 30" in ground (now in place with 3/4" I.P. in side) from which a:

- 1/2" dowel in top of 36" Fir stump bears S26E 39.6 ft.; now in place.
- Boat spike in top of 48" Fir stump bears S84 1/2 E 24.0 ft.; stump in place, spike missing.

RESTORED

Var. 21 1/2 E

Set 4" x 4" x 65" white painted Cedar post 1.0 ft. SW of above pipe from which a:

- 6" Fir bears S21E 57.5 ft.; scribed T2N R6W S34 BT RS401.
- 5" Fir bears S45W 32.1 ft.; scribed X BT.
- 4" Fir bears N3E 27.9 ft.; scribed X BT.

Oregon State Forestry Department metal location poster on 5" Fir BT.  
Also poster on 4" x 52" white painted Cedar post approximately 184 ft. North on north edge of road.

Dated February 15, 1963

Restored by



*Richard A. Morris*  
MAY 10, 1957  
Richard A. Morris  
401

Present and witnessed by M. Trout  
H. Russell

8/6/4