

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RE-ESTABLISHED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY  
(See official plat)

One Quarter corner common to Sections 20 and 21, T3S, R8W,  
W.M., Tillamook County, Oregon.

No evidence of original corner found.

RE-ESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE  
BOARD OF FORESTRY 1/4 S20 S21 1961 RS401", 33 inches in ground, and from  
which a:

13" Fir bears S62 1/2 W 26.3 ft.; scribed 1/4 S20 BT.

13" Fir bears S67 E 38.8 ft.; scribed 1/4 S21 BT RS401.

Set 4" x 4" x 52" white painted Cedar post 1.0 ft. S.E. of corner pipe.  
Oregon State Forestry Department metal location poster on 16" Fir N20E 1.6'.

ESTABLISHED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Center North One Sixteenth corner for Section 16, T3S, R8W,  
W.M., Tillamook County, Oregon.

ESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE  
BOARD OF FORESTRY N 1/16 C---C S16 1961 RS401", 33 inches in ground,  
and from which a:

46" Fir bears S43 1/2 W 68.8 ft.; scribed CN 1/16 S16 BT RS401.

24" Hemlock bears N31W 55.7 ft.; scribed CN 1/16 S16 BT.

Set 4" x 4" x 52" white painted Cedar post 1.0 ft. S.W. of corner pipe.  
Oregon State Forestry Department metal location poster on 13" Alder S51W 7.4'.


Dated January 22, 1962

By

*Harold J. Russell*  
Harold Russell, Engineering Technician

under my direction.

Present and witnessed by A. Duncan  
E. Danialson



*Richard A. Morris*  
MAY 10, 1957  
Richard A. Morris  
401

Book I

451

1/4 Cor  
F. S. 20  
20-3-98

Cor. N. 1/16  
16-3-58