

County Surveyor's Record, Tillamook County Oregon

1/4 CORNER
S. 1/4
11-5-59

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One Quarter corner common to Sections 11 and 14, T6S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 12" Fir bears South 16 lks.; now 12" rotted snag, scribes 1/4 and BT remaining.
- 8" Fir bears N68°W 20 lks.; now missing.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S11 S14 1961 RE2311", 32 inches in ground, and from which a:

- 8" Fir bears N76 1/2°W 42.2 ft.; scribed 1/4 S11 BT RE2311.
- 7" Fir bears S51 1/2°E 42.2 ft.; scribed 1/4 S14 BT.
- 18" Stump with scribes BM 880.6 bears west 27.6
- Center Line of logging road bears North 15.0 ft. Course N60°W.
- Oregon State Forestry Department metal location poster on 3" Cherry N45 1/2°E 23.7
- Set 4 x 4 x 72" white painted Cedar post bears 1.0 ft. NW of corner pipe.

Dated March 5, 1962

Restored by *Billy E. Davis* under my direction.
Billy E. Davis, Transitman

Present and witnessed by R. Schulson

