

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 14 and 23,  
T2S, R 9W, W.M., Tillamook County, Oregon

ORIGINAL

Post (now missing) from which a:

- 10" Hemlock bears N8E 42 lks.; now just root hole in place.
- 12" Hemlock bears S22° 30'W 6 lks.; now 24" stub 3' high, scribes BT remaining.

RESTORED

Var. 21½E


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S14 S23 1958 RS401," 33 inches in ground, and from which a:

- 10" Fir bears S33E 15.0 ft.; scribed 1/4 S23 BT RS401.
- 5" Hemlock bears N4E 15.5 ft. scribed 1/4 S14 BT.


Oregon State Board of Forestry metal location poster on 5" Hemlock BT.  
Set 3" x 4" x 60" white painted cedar post 1' S. E. of pipe.

Dated May 28, 1958

Restored by



*Richard A. Morris*



Present and witnessed by Robert Sturm  
Harold Russell  
Lloyd Geraths

Book I