

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 20 and 21, T3N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 30" Hem bears N45E 4 lks.; now 40" uproot, $\frac{1}{2}$ S visible on partially exposed face.
- 20" Hem bears S20W 21 lks.; now 20" badly rotted stub, 30" high, face and scribes rotted away.

RESTORED

Var 21 $\frac{1}{2}$ E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S20 S21 1969 RS707", 31 inches in ground, and from which a:

- 25" Hem bears S6 $\frac{1}{2}$ E 19.8 ft.; scribed $\frac{1}{4}$ S21 BT RS707.
- 16" Hem bears S33W 44.6 ft.; scribed $\frac{1}{4}$ S20 BT.
- Logging road bears North 164 ft., N70E by S70W.
- Dry ravine bears South 45 ft.; slopes west.
- Found a 3/4" iron pipe west 10.4'.


Set 4" x 4" x 50" white painted Cedar post 1.0 ft. SE of corner pipe. Oregon State Forestry Department metal location poster on 25" Hem BT. Also poster on 6' Fir stump on North edge of logging road North 181.5'

Dated May 29, 1970

Restored by

Present and witnessed by C. Curl
B. Henderson

REGISTERED
OREGON
LAND SURVEYOR



JULY 9, 1965
HAROLD J. RUSSELL
707