

REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY
4907 Third St., Tillamook, Oregon 97141

One quarter corner common to Sections 7 and 18, T2S, R6W, W.M., Tillamook County, Oregon.

ORIGINAL by James H. Mather, September 12, 1892.
Post; missing.

- 42" Fir bears N20E 48 lks.; now a 44"x 4 ft. high badly rotted stump with no evidence of face remaining. Distance now 30.9 ft.
- 24" Hemlock bears S30E 18 lks.; missing, point falls in old cat road.

RESTORATION by Arnold G. Gibson LS359, April 30, 1957 (Book 2, page 348 Tillamook Co. Records.)

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 30" in ground, on North edge of cat road, in mound of stone; now 38" in ground, in place.

- Original 42" Fir; scribes 1/4 S7 BT RS359 visible.
- 68" Fir stump bears S18E 27.6 ft.; now 6 ft. high badly rotted with scribes 1/4 S18 BT visible.
- Metal location poster on a 50"x6 ft. high Fir stub bears N72E 22.5 ft; now 10 ft. high, in place.

REWITNESSED by Larry D. Evans, Cadastral Surveyor, Group #885, August, 1976 unrecorded.

- 29" Fir bears S58E 69.1 ft. to face; exposed portions of scribes. This tree was about 16" when scribed.

NOTE: In Volume 638, page 76 of the BLM notes it states "no suitable trees available", however I found a BLM poster on a 29" Fir dated August, 1976 posted by LDE N60 1/2W 106 lks. to 1/4 corner. Scribes on Fir date to about 1976 by ring count.

REWITNESSED October 10, 1990

Var. 21 1/2 E

From above pipe with marks "LS1998 1990" added, a:

- 10" Fir bears N14E 23.5 ft. to face; scribed 1/4S7BT.

Metal location poster on new BT.
3/4" brass washer marked "LS1998" nailed to face of new BT.
Found 4"x4"x40" white painted Cedar post .8 ft. SE of pipe.
Present and witnessed by Clifford R. Foster.

Rewitnessed by David B. Buchholz under my direction.
David B. Buchholz, LS2272

