

REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY
4907 Third St., Tillamook, Oregon 97141

Section corner common to Sections 1, 2, 35 and 36, T1&2S, R7W, W.M.,
Tillamook County, Oregon.

ORIGINAL by Albert P. Wilson, May 18, 1891.

Post; missing.

22" Hemlock bears N23 1/2W 18 lks.; missing.

14" Hemlock bears N31E 23 lks.; now badly rotted stump with axe
work visible on burnt out face.

24" Hemlock bears S18W 34 lks.; now root hole.

20" Hemlock bears S68 1/2E 23 lks.; now badly rotted root crown.

NOTE: Distance measured from center of BTs.

RESTORATION by Louis W. Amort RE2311, May 7, 1952 (Book 2, page 196,
Tillamook County Records).

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 30" in ground, in
mound of stone; in place.

50" Fir snag bears S74E 23.0 ft.; now a 4 ft. high badly rotted
stump with scribes T2S R7W S1 BT visible.

38" Fir snag bears N65W 40.8 ft.; now a 7 ft. high badly rotted
stump with scribes T1S R7W S35 BT RE2311 visible.

50" Fir stump bears S79 1/2W 4.8 ft.; now 7 ft. high badly rotted
with scribes T2S R7W S2 BT visible.

REWITNESSED October 16, 1990

Var. 21 1/2E

From above pipe with marks "LS1998 1990" added, a:

6" Fir bears N15E 9.9 ft. to face; scribed T1SR7WS36BT.

11" Fir bears S42 1/2E 29.3 ft. to face; scribed T2SR7WS1BT.

6" Fir bears S26W 24.2 ft. to face; scribed T2SR7WS2BT.

17" Fir bears N62 1/2W 24.6 ft. to face; scribed T1SR7WS35BT.

Metal location poster on new BTs.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

Present and witnessed by David B. Buchholz and Clifford R. Foster.

Rewitnessed by

