

REWITNESSED CORNER FOR OREGON DEPARTMENT OF FORESTRY  
4907 Third St., Tillamook, Oregon 97141

One quarter corner common to Sections 4 and 9, T1S, R7W, W.M.,  
Tillamook County, Oregon.

ORIGINAL by Albert P. Wilson, November 1, 1891.  
Post; missing.

- 24" Hemlock bears N78W 44 lks.; now a 20" badly rotted stump  
with no scribes visible.
- 20" Hemlock bears S06W 45 lks.; now a 24" badly rotted stump  
with scribes 4 S BT visible.

RESTORATION by Richard A. Morris LS401, August 4, 1959 (Book 1,  
page 389, Tillamook Co. Records.)

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 34" in  
ground, in small mound of stone; in place.

- 60" Fir stump bears S50E 64.9 ft.; now badly rotted with  
scribes 1/4 S9 BT RS401 visible.
- 66" Fir stump bears N20 1/2E 33.1 ft.; now burnt and badly  
rotted with scribes 1/4 S4 BT visible.
- 4"x4"x48" white painted Cedar post 1.4 ft. NE of corner  
pipe; in place.

REWITNESSED June 19, 1992

Var. 19 1/2 E

From above pipe with marks "LS1998 1992" added, a:

- 14" Fir bears N62 1/2E 38.7 ft. to face; scribed 1/4S4BT.
- 23" Fir bears S27 1/2W 41.9 ft. to face; scribed 1/4S9BT.

Metal location poster on new BTs.  
Also 1959 tag on 60" Fir stump BT.  
3/4" brass washer marked "LS1998" nailed to face of new BTs.  
Present and witnessed by David B. Buchholz.

Rewitnessed by

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*(Anthony J. Klosterman)*  
OREGON  
JULY 16, 1982  
ANTHONY J. KLOSTERMAN  
1998

