

RESTORED CORNER FOR OREGON DEPARTMENT OF FORESTRY  
4907 Third St., Tillamook, Oregon 97141

One quarter corner common to Sections 14 and 23, T1S, R7W, W.M.,  
Tillamook County, Oregon.

ORIGINAL by Albert P. Wilson, October 9, 1891.  
Post; missing.

20" Hemlock bears S06 1/6W 39 lks.; now a 16" x 3 ft. high  
badly rotted stub with no scribes visible.  
18" Hemlock bears N34E 30 lks.; missing.

RESTORATION by Louis W. Amort RE2311, March 23, 1954 (Book 1,  
page 129, Tillamook Co. Records.)

1 1/2" x 36" galvanized iron pipe with 3" bronze cap, 28" in  
ground, in 5 ft. x 4 ft. x 10" mound of stone; found pipe  
torn out of ground and stone mound scattered by a dozer.

54" Cedar snag bears N20 1/2E 21.7 ft.; now an 80" x 4 ft.  
high rotted hollow stump with scribes BT visible.  
58" Cedar snag bears S64W 31.0 ft.; now a 64" x 4 ft. high  
rotted stump with scribes 3 BT visible.  
4"x4"x60" white painted Cedar post 1.5 ft. SE of corner  
pipe; down and out of place.

RESTORATION August 26, 1992

Var. 19 1/2 E

Set a 1 1/2" x 30" Aluminum pipe with 3 3/4" cap marked " STATE  
OF OREGON DEPARTMENT OF FORESTRY T1S R7W 1/4 S14 S23 1992 LS  
1998", 18" in ground in 4 ft. x 5 ft. x 20" high mound of stone,  
from which a:

24" Fir bears S66E 46.2 ft. to face; scribed 1/4S23BT.  
20" Fir bears S03W 50.7 ft. to face; scribed 1/4S23BT.  
21" Fir bears N72W 15.4 ft. to face; scribed 1/4S14BT.

Metal location poster on new BTs.

3/4" brass washer marked "LS1998" nailed to face of new BTs.  
Corner pipe set on South edge of cat road, course S52E by N72W.  
Present and witnessed by Clifford R. Foster and Joe M. Justice.

Rewitnessed by David B. Buchholz under my direction.  
David B. Buchholz, LS2272

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Anthony J. Klosterman*

OREGON  
JULY 16, 1982  
ANTHONY J. KLOSTERMAN  
1998

