

REWITNESSED CORNER FOR OREGON DEPARTMENT OF FORESTRY  
4907 Third St., Tillamook, Oregon 97141

One quarter corner common to Sections 8 and 9, T2N, R7W, W.M.,  
Tillamook County, Oregon.

ORIGINAL by Henry Meldrum, July 31, 1893.

16"x11"x9" basalt stone 11" in ground with 1/4 on west face;  
did not locate, but did not disturb stone mound.

24" Hemlock bears S79W 20 lks.; now a 36"x3 ft. high badly  
rotted stub with no scribes visible.

18" Hemlock bears S82E 44 lks.; now a 14"x4 ft. high badly  
rotted stump with portions of scribes /4 BT visible.

RESTORATION by Louis W. Amort RE2311, October 6, 1953 (Book 2,  
page 304, Tillamook County Records).

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 30" in  
ground, on south side of original stone, in mound of stone;  
now leaning to the East in apparent proper location for  
corner point.

40" Fir stump bears S09W 18.0 ft.; now 5 ft. high and rotted  
with scribes 1/4 S8 BT visible.

32" Fir stump bears N73E 26.8 ft.; now 5 ft. high and rotted  
with scribes 1/4 S9 BT RE2311 visible.

4"x4"x48" white painted Cedar post 2.3 ft. South of pipe; in  
place.

REWITNESSED October 12, 1992

Var. 19 1/2 E

From above pipe with marks "LS1998 1992" added a:

11" Fir bears N25E 16.0 ft. to face; scribed 1/4S9BT.

12" Fir bears S58 1/2E 20.5 ft. to face; scribed 1/4S9BT.

12" Fir bears S29W 12.75 ft. to face; scribed 1/4S8BT.

9" Fir bears N41W 7.2 ft. to face; scribed 1/4S8BT.

Metal location poster on new BTs.

Also 1953 metal location poster on Amort's 32" Fir stump BT.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

Present and witnessed by Clifford R. Foster.

Rewitnessed by David B. Buchholz under my direction.  
David B. Buchholz, LS2272

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Anthony J. Klosterman*

OREGON  
JULY 16, 1982  
ANTHONY J. KLOSTERMAN  
1998

