

REWITNESSED CORNER OREGON DEPARTMENT OF FORESTRY
4907 Third St., Tillamook, Oregon 97141

One quarter corner common to Sections 25 and 36, T1S, R7W, W.M.,
Tillamook County, Oregon.

ORIGINAL by Albert P. Wilson, September 14, 1891.
Post; missing.

30" Hemlock bears N81 1/2E 70 lks.; now a 40" x 10' high
badly rotted stub with portions of scribes visible.
8" Hemlock bears S8W 93 lks.; missing.

RESTORATION by Arnold G. Gibson LS359, April 20, 1956 (Book 2,
page 336, Tillamook Co. Records.)

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 34" in
ground, in mound of stone; in place.

29" Fir snag bears N07E 78.6 ft.; now 40' high, badly rotted
with portions of scribes 1/4 S25 BT visible.
54" Fir stump bears S16E 50.0 ft.; now 4' high and rotted
with scribes 1/4 S36 BT RS359 visible.
1.0 ft. Creek bears North 10.0 ft. course East; now 21.0 ft.
distance, course N60E from S48W.

REWITNESSED January 26, 1994

Var. 19 1/2 E

From above pipe with marks "LS1998 1994" added, a:

14" Fir bears N14 1/4E 54.6 ft. to face; scribed 1/4S25BT.
10" Hemlock bears S80 1/2E 59.1 ft. to face; scribed
1/4S36BT.
15" Fir bears S42 1/2W 26.0 ft. to face; scribed 1/4S36BT.
23" Fir bears N18W 51.1 ft. to face; scribed 1/4S25BT.

Metal location poster on new BTs.

1956 post bears South 1.3 ft.

Also 1956 metal location poster on Gibson's 29" Fir snag BT.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

Present and witnessed by Clifford R. Foster. and Greg K. Miller.

Rewitnessed by David B. Buchholz under my direction.
David B. Buchholz, LS2272

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Anthony J. Klosterman
OREGON
JULY 16, 1982
ANTHONY J. KLOSTERMAN
1998



Expires 6/30/95