

REWITNESSED CORNER FOR OREGON DEPARTMENT OF FORESTRY
4907 Third St., Tillamook, Oregon 97141

One quarter corner common to Sections 30 and 31, T3N, R7W, W.M.,
Tillamook County, Oregon.

ORIGINAL by Henry Meldrum, December 10, 1891

14"x12"x6" Basalt stone 10" in ground with 1/4 on north face;
found 14"x12"x6" Basalt stone on north edge of pipe with
no marks visible.

11" Hemlock bears S36°E 17 lks.; now a 14" x 1½ ft. high
badly rotted stub with no sign of face visible.
26" Hemlock bears N41°W 81 lks.; now a 18" x 2½ ft. high
badly rotted stump with no scribes visible.

RESTORATION by Louis W. Amort RE2311, April 22, 1952 (Book 2,
page 156, Tillamook County Records).

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 30" in
ground, in mound of stone; in place.

30" Fir snag bears S56°E 25.0 ft.; now 5 ft. high and
rotted with scribes 1/4 S31 BT RE2311 visible.

30" Fir stump bears N15°W 70.9 ft.; now 5 ft. high with
scribes 1/4 S30 BT visible.

Metal location poster on 41" Fir stump S88°W 37 lks.; in
place.

REWITNESSED January 11, 1999

From above pipe with marks "LS1998-1999" added a: Var. 19½°E

11" Fir bears N63½°E 19.85 ft. to face; scribed 1/4S30BT.

9" Fir bears S32°E 15.96 ft. to face; scribed 1/4S31BT.

12" Fir bears S84¼°W 22.61 ft. to face; scribed 1/4S31BT.

12" Fir bears N09¼°W 4.27 ft. to face; scribed 1/4S30BT.

Metal location poster on new BTs.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

6 ft. Orange carsonite post bears SW 1.5 ft.

Present and witnessed by Clifford R. Foster, David W. Wells and
Colleen R. Holmen.

Restored by David B. Buchholz under my direction.

David B. Buchholz, LS2272



SURVEYED BY:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Anthony J. Klosterman

OREGON
July 21, 1982
Anthony J. Klosterman
1998

4907 THIRD STREET
TILLAMOOK, OR 97141
EXPIRES JUNE 30, 1999