

Morris  
Davis  
3

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Section corner common to Sections 2, 3, 10 and 11, T.3N,  
E.10W, W.M., Tillamook County, Oregon.

ORIGINAL.

Post (now missing Point Falls in cat road) from which a:

- 40" Cedar bears N50°W 28 lks.; now 46" stump, bottom of face remaining, also axe marks on butt log (now bears N13W, see below).
- 36" Hemlock bears S45°E 49 lks.; now 34" stump, bottom of face remaining (now bears S50E, see below).
- 36" Hemlock bears S31°W 70 lks.; now badly decayed stump (now bears S20W, see below).

P

Note: Survey in 1893 found above BT's with bearings and diameters to be;

- 40" Cedar bears N13°W 28 lks.
- 30" Hemlock bears S50°E 49 lks.
- 25" Hemlock bears S20W 70 lks.

RESTORED

VAR. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R10W S2 S3 S10 S11 1963 RS 401", 32 inches in ground, and from which a:


- 19" Hemlock bears S88E 31.2 ft.; scribed T3N R10W S11 BT.
- 26" Hemlock bears N48E 12.3 ft.; scribed T3N R10W S2 BT.
- 23" Hemlock bears N64W 32.0 ft.; scribed T3N R10W S3 BT RS 401.
- 5" Cedar bears S25W 21.3 ft.; scribed T3N R10W S10 BT.

Oregon State Forestry Department metal location poster on 26" Hemlock BT.  
Set 4" x 4" x 60" white painted Cedar post 1" ft. NE of corner pipe.

Dated March 27, 1963

Restored by Billy E. Davis under my direction.  
Billy E. Davis, Transitman

Present and witnessed by A. Duncan  
D. Fletcher



Richard A. Morris  
MAY 10, 1957  
Richard A. Morris