

Morris
29

RESTORED CORNER FOR STATE OF OREGON—DEPARTMENT OF FORESTRY

One Quarter corner common to Sections 25 and 36, T2S, R7W,
W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 20" Hemlock bears $S43^{\circ}30'E$ 15 lks.; now 22" stump, scribes $1/4 S$ exposed.
- 24" Hemlock bears $N12^{\circ}30'E$ 12 lks.; now 27" stump, no face remaining, chopped out "E" cruiser mark.

P

RESTORED

Var. $21\frac{1}{2}E$

Set $1\frac{1}{2}''$ x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY $1/4 S25 S36 1962 RS401$ ", 32 inches in ground, in mound of stone, and from which a:

- 27" Fir bears $N74\frac{1}{2}^{\circ}E$ 178.1 ft.; scribed $1/4 S25 BT RS401$.
- 72" Fir stump bears $S85\frac{1}{2}^{\circ}E$ 144.4 ft.; scribed $1/4 S36 BT$.

Oregon State Forestry Department metal location poster on original 20" BT.
Set 4" x 4" x 56" white painted Cedar post 2 ft. southwest of corner pipe.

Dated December 14, 1962

Restored by *Bill E. Davis* under my direction.
Bill E. Davis, Transitman

Present and witnessed by A. Duncan

REGISTERED
OREGON
LAND SURVEYOR

Richard A. Morris

MAY 10, 1957
Richard A. Morris
401

