

BAYSIDE SURVEYING

11765 HWY 101 South
Tillamook, Oregon 97141

Terry L. Jones
503-842-5551
Fax 503-842-5552

April 2002

REWITNESS
SECTION CORNER COMMON TO SECTIONS 33, 34, 4 & 3
TOWNSHIP 2 and 3 SOUTH, RANGE 8 WEST

I found:

2½" BLM brass cap on 1½ galvanized iron pipe stamped "T2S R8W S33 S34 S4 S3 T3S 1956" in stone mound. (See BLM field notes.)

From which:

27" Hemlock with healed face bears N36°E 90 lks. (14" Hemlock bears N36°E 90 lks. See BLM field notes.)


22" Hemlock with healed face bears S56°E 41 lks. (10" Hemlock bears S56°E 41 lks. See BLM field notes.)

22" Hemlock with healed face bears S22.5°W 57 lks. (14" Hemlock bears S22.5°W 57 lks. See BLM field notes.)

18" Hemlock with healed face bears N54.5°W 50 lks. (14" Hemlock bears N54.5°W 50 lks. See BLM field notes.)

Corner & BTs on spur ridge above (North of) road, between two creeks.

In the presence of Terry Jones, Dallas Esplin



Terry L. Jones

