



**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
Tillamook County Surveyor's Office

<b>SECTION:</b> The NE ¼ SE¼ of Section 30	<b>TOWNSHIP</b> 1 South	<b>RANGE</b> 9 West
<b>COUNTY:</b> Tillamook		<b>DATE:</b> 07-07-06
<b>CORNER DESIGNATION:</b> Reference monument set for a found tack in the top of a plant boarder set over a 1-1/4" iron pipe with wood plug and nail.	<b>(Please check one)</b>	
	<input type="checkbox"/>	Condition Report Only
	<input type="checkbox"/>	Not Found
	<input checked="" type="checkbox"/>	Renewed
	<input type="checkbox"/>	Unrecorded
<input type="checkbox"/>	Surveyed In	
<input checked="" type="checkbox"/>	Referenced Out	
<b>Previous Rewitnesses, Restorations and Surveys, etc.:</b> Map A-6113 by W.E. Anderson established original position of centerline monument.		
<b>Found Monument(s) and Accessories (Condition &amp; Source):</b> Found a tack in the top of a plant boarder set over the top of a 1-1/4" diameter iron pipe with wood plug and nail, 0.80' below the ground. The tack and iron pipe were found to be in good condition.		
<b>Monument Set (Procedures and Description):</b> A 2" diameter Tillamook County brass disk, stamped as shown hereon, was set at the road surface, along the centerline of Alder Lane a distance of 40.00' East from the existing tack. Set a cow magnet in anchoring cement under the brass disk.	<b>Sketch of Set Monument:</b> 	
<b>Other new accessories set:</b> No new accessories set.		
<b>New Bearing Trees:</b> No bearing trees set.		
<b>Location &amp; Comments:</b> Reference monument located on the East right-of-way line of Evergreen Drive and the centerline of Alder Lane.		
<b>Firm / Agency</b> Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE	<b>SURVEYOR'S SEAL</b>   <i>Danny R. McNutt</i> C.S.	
<b>Party Chief:</b> Joe Jensen, Survey Supervisor		
<b>Notes:</b>		
<b>Witness:</b> Danny R. McNutt, Tillamook County Surveyor		

