



OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: Section 27	TOWNSHIP 1 South	RANGE 9 West
COUNTY: Tillamook		DATE: 08-14-07
CORNER DESIGNATION: The Northeast corner of the Champion Donation Land Claim #39, Section 27, Township 1 South, Range 9 West, W.M., Tillamook County, Oregon.		(Please check one)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input checked="" type="checkbox"/> Reset at surface
<input type="checkbox"/> Referenced Out		
Previous Rewitnesses, Restorations and Surveys, etc.: Rewitness Book 7, Page 75, Rewitness card #226, Tillamook County Survey Records.		
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Tillamook County Brass cap in an 8" diameter cast iron monument case stamped as shown in Rewitness Book 7, Page 75. The monument box was filled with concrete and a monument was set at the road surface (see note below).		
This monument is now lying beneath the road surface. Two references listed on Rewitness Book 7, Page 75 are now gone. The telephone pole at N. 80 E. 87.13' is gone and the replacement pole #18 is now gone. The 4" x 4" x 48" post located South 16.0' is now gone. All other references listed in said Book 7, Page 75 were found as reported.		
Monument Set (Procedures and Description): I set a 2" diameter Tillamook County Surveyor brass disk in concrete at road surface and stamped as shown hereon.		Sketch of set Monument:
		
Other new accessories set: No new accessories set.		
New Bearing Trees: No bearing trees were marked.		
Location & Comments: This corner is located in the apparent centerline of Hughey Lane.		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE		SURVEYOR'S SEAL 
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor		
Notes:		
Witness: Danny R. McNutt, PLS 49230, Tillamook County Surveyor		

