


OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 32 and 5	TOWNSHIP: 3N and 2N	RANGE: 9 West
COUNTY Tillamook		DATE: 1/4/2008
CORNER DESIGNATION: The south one quarter section common to sections 32, T3N-R9W of the W.M. and the north 1/4 of section 5, T2N-R9W. of the W.M.		(Please Check One)
		<input checked="" type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input type="checkbox"/> Rewitness
		<input type="checkbox"/> Not Found
		<input type="checkbox"/> Reset
		<input type="checkbox"/> Referenced Out
Previous Rewitnesses, Restorations, Surveys, etc.: Rewitness Book 6 Page 401-Tillamook County Survey Records Rewitness card #65-Tillamook County Survey Records		
Found Monument(s) and Accessories(Condition & Source): Found a 3" Tillamook County Brass Cap in a 8" clay tile and cement in good condition. It is close to the ditch line of Foss Rd. (See County Surveyor Rewitness card #65) Found a 96" hat section post-S. 20° E. 1.4' w/yellow metal location tag. Also found were two 5/8" iron rods in West bound lane of Foss County Rd. being S. 66° E. at 38.14', the second was S. 24° 23' 30" W. at 44.63'. Found 72" Cedar stump N. 70° W. 9.60' to face-Marked w/sign " Bearing Tree", no visible scribe marks remaining. Found 24" Hemlock S. 18° E. 56.55'-Now 47", retagged w/yellow metal location tag at record position.		
Monument Set(Procedures & Description): n/a		
Other New Accessories Set: n/a		
New Bearing Trees: n/a		
Location & Comments: This corner is located approximately 22' from the North side of Foss County Rd.		Surveyor's Stamp 
Firm/Agency: Tillamook County Surveyor's Office		
Address: 201 Laurel Avenue-Tillamook, Oregon		
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor		
Notes:		Office Use Only
Witness(es): Danny R. McNutt, PLS 49230, Tillamook County Surveyor Randy Wilson Survey Technician		