


OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 34, 3	TOWNSHIP 1 and 2 South	RANGE 10 West	
COUNTY: Tillamook		DATE: 12-05-08	
CORNER DESIGNATION: The 1/4 corner common to T. 1 S., R. 10 W., Section 34 and T. 2 S., R. 10 W., Section 3.		(Please check one)	
		<input type="checkbox"/>	Condition Report Only
		<input type="checkbox"/>	Restoration
		<input checked="" type="checkbox"/>	Rewitness
		<input type="checkbox"/>	Unrecorded
		<input type="checkbox"/>	Reset at surface
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0053 Page 0106.0, GLO Pg. 13, 1857, Quarter corner was set using found monument and original bearing trees in Re-witness card #437 in 1976.			
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Brass Cap good condition, in a 10" tile casing with cement. The monument is stamped as shown hereon. (G.L.O.) – Did not find the 32" diameter Hemlock at record position. (G.L.O.) – Did not find the 48" diameter Hemlock at record position. (Re-witness Card #437) – Found 35" diameter (12"), Hemlock, at S 55° E 39.5' to face (41.3) Feet. Scribed "B.T.", Tagged. Found & replaced "Do not cut" tag on tree. (Re-witness Card #437) – Did not find the 24" Hemlock at record position. Found 6" X 6" white cedar post 1.2' North of the corner. Found hat section post w/ paddle N 60° E 1.7'.			
Monument Set (Procedures and Description): Not applicable.	Sketch of Found Monument: 		
New accessories set:			
New Bearing Trees set: 16" diameter Hemlock bears N 33° E 16.5 Feet, Scribed "T1S R10W 1/4 S34 BT", Tagged, Painted. All new bearing trees have a nail and washer marked, "Till. Co. Surveyor", in face of blaze, between B and T in scribe. Also re-scribed SE BT.			
Location & Comments: Corner is located approx. 500' South of Highway 131.			
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL <div style="border: 1px solid black; padding: 5px; display: inline-block;"> REGISTERED PROFESSIONAL LAND SURVEYOR </div> <i>Joseph V. Jensen</i> <div style="border: 1px solid black; padding: 5px; display: inline-block;"> OREGON JANUARY 10, 2006 JOSEPH V. JENSEN 60067 </div> RENEWAL DATE: 08-30-09	
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor			
Notes:			
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor. Michael R. Rice, L.S.I. 16723, Survey Technician			

