



**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
**Tillamook County Surveyor's Office**

<b>SECTION:</b> W.C. to M.C. Sections 7 and 8	<b>TOWNSHIP:</b> 1 South	<b>RANGE:</b> 10 West
<b>COUNTY:</b> Tillamook		<b>DATE:</b> 09-03-09
The Witness Corner to the Meander Corner which is common to Sections 7 and 8, Township 1 South, Range 10 West, W.M., Tillamook County, Oregon.		<b>(Please check one)</b>
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input checked="" type="checkbox"/> Brass Cap set at surface
<b>Previous Rewitnesses, Restorations and Surveys, etc:</b> Rewitness Book 7, Page 85, Rewitness Book 4, Page 68, Book S3, Page 152, Field Notebook "H", Page 67, Survey maps A-7, A-153, A-658, A-1024, A-1111, A-2305, A-4099, A-4489, A-4957, A-4958, A-4959, A-4960, A-4961, A-6956, B-226, B-2272, P-503, F-13-28, F-24-11, F-26-03, Tillamook County Survey Records.		<input checked="" type="checkbox"/> Referenced Out
<b>Found Monument(s) and Accessories (Condition &amp; Source):</b> Found a 3" diameter Tillamook County Surveyors Brass Cap in an 8" diameter cast iron monument case encased in concrete. The 3" diameter brass cap is now covered due to an asphalt paving project and is now considered a subsurface monument. The subsurface monument is stamped as shown in Rewitness Book 7, Page 85. ( ) – Indicates record value from Rewitness		
<b>Monument Set (Procedures and Description):</b> Set a 2" diameter brass cap in concrete at the road surface. The monument is stamped as shown hereon.		<b>Sketch of Monument Set at Surface:</b> 
<b>New accessories set:</b> Prior to the covering of the 3" diameter Tillamook County Surveyors Brass Cap, two reference monuments were set as points on line to the monument. A 3/4" X 10" rebar with center punch set on the Northerly edge of Bay Ocean County Road bears North 14° East (compass bearing) a distance of 29.65'. Also a 5/8" rebar with yellow plastic cap stamped "TILLAMOOK CO RANDOM" which bears South 14° West (compass bearing) a distance of 34.64'. This reference monument is located in an existing gravel driveway.		
<b>New Bearing Trees set:</b> No new bearing trees were set.		
<b>Location &amp; Comments:</b> This corner is located in the apparent centerline of Bay Ocean County Road and approximately 280' Northeasterly of the intersection of Bay Ocean-Oceanside Road.		
<b>Firm / Agency</b> <b>Address:</b> TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		<b>SURVEYOR'S SEAL</b>
<b>Party Chief:</b> Joe Jensen, PLS 60067, Survey Supervisor		 RENEWAL12-31-2010
<b>Notes:</b> Digital images were taken of both the surface and subsurface monument.		
<b>Witnesses:</b> Danny R. McNutt, PLS 49230, Tillamook County Surveyor. Michael R. Rice, L.S.I. 16723, Survey Technician		

