

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: SW 17	TOWNSHIP 2 South	RANGE 7 West	
COUNTY: Tillamook		DATE: 11-2-09	
CORNER DESIGNATION: The Section Corner common to Sections 17, 18, 19, and 20, T. 2 S., R. 7 W., W.M.		(Please check one)	
		<input type="checkbox"/>	Condition Report Only
		<input type="checkbox"/>	Restoration
		<input checked="" type="checkbox"/>	Rewitness
		<input type="checkbox"/>	Unrecorded
		<input type="checkbox"/>	Reset at surface
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0345 Page 325, (GLO Book 2S7 Page 51) (1891), Tillamook County Survey Records; Rewitness Book 2, Page 86 (1951), Rewitness Book 6, Page 374 (1988), Tillamook County Survey Records.			
Found Monument(s) and Accessories (Condition & Source): Found a 3" O.S.B.F. Brass Cap, good condition, up 0.5', in a mound of stone. The monument was set in Rewitness Book 2, Page 86 (1951). The monument is stamped as shown hereon. The original post is missing. (G.L.O.) – Did not find the (28" Hemlock bears S 66 3/4° W 27 lks. [17.82']). (G.L.O.) – Did not find the (22" Hemlock bears S 23 1/2° E 36 lks. [23.76']). (G.L.O.) – Did not find the (6" Vine Maple bears N 65 1/2° W 65 lks. [42.9']). (G.L.O.) – Did not find the (10" Barberry bears N 17° E 29 lks. [19.14']). (Book 2, Page 86) – Found rotten (72" Fir Stump), 3' tall, (bears S 54° E 139.0'), scribing partially visible. (Book 2, Page 86) – Found down and rotten (89" Fir Snag bears N 68° E 79.5'), no marks visible. (Book 6, Page 374) – Found 14" Fir (was 10"), (bears N 80° E 13.1'), healed scar and yellow metal location tag. (Book 6, Page 374) – Found 12" Fir Snag (was 10"), 25' tall, (bears S 34 1/2° E 9.6'), healed scar and tag affixed. (Book 6, Page 374) – Found 19" Fir (was 12"), (bears S 81° W 5.8'), healed scar and tag affixed. (Book 6, Page 374) – Found 16" Fir (was 10"), (bears N 18° W 15.1'), healed scar and tag affixed. () Indicates record information, Tillamook County Survey Records. [] Indicates converted value from links to feet.			
Monument Set (Procedures and Description): Not applicable.		Sketch of Found Monument:	
New accessories set: Set 120 lbs. of concrete in a 12" dia. cylinder around monument. Set 72" hat section post with a yellow metal location tag, 3.0' South from monument. Reset rock collar.			
New Bearing Trees set: *17" dia. D. Fir bears S 30° E 25.8', scribed "T2S R7W S20 BT", tagged and painted. *Indicates a yellow metal location tag affixed and a nail with an aluminum washer marked "Till. Co. Surveyor" between the scribed "B" and "T".			
Location & Comments: Monument is located approximately 150' South of the East Fork of Trask Road.			
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL	
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor			
Notes: Digital images were taken of the monument, the found bearing trees and the new accessories.			
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician		RENEWAL DATE: 06-30-2011	

