

Index

CORNER RECORD (SEARCH)

File No. H-21 PROJ. NO. Panther #2 CORNER S 1/16
 TOWNS. 6S RANGE 10W R.D. Hebo COUNTY Tillamook GCDB# 600520
 MERID. W.M. FOREST Siuslaw STATE Oregon

<p>CORNER DIAGRAM</p> <p>N ↑</p>	<p>DESCRIBE CORNER MONUMENT FOUND</p> <p>Found standard 3-1/4" USDA Aluminum Cap on 2-1/2" Aluminum Pipe, Found laying on top on windfall BT's roots having been lifted when tree fell Reset by survey, see below</p>															
<p>PHOTO IDENTIFICATION DATA</p> <p>Photo No. <u>None</u></p> <p>Filed At. <u>None</u></p> <p>Obj. Ident. <u>None</u></p> <p>Ident. By <u>None</u></p> <p style="text-align: center;">Signature _____</p>	<p>DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND</p> <table border="1"> <thead> <tr> <th>DIA</th> <th>TYPE</th> <th>BEARS</th> <th>DIST</th> <th>FACE/MARKINGS</th> </tr> </thead> <tbody> <tr> <td>17"</td> <td>Hemlock Sn.</td> <td>N 71°45' W</td> <td>11.5 FT</td> <td>10 FT tall Snag, Healed Double Blaze</td> </tr> <tr> <td>10"</td> <td>Hemlock W.</td> <td>S 85° E<R></td> <td>4.3 FT<R></td> <td>Windfall, laying on face, large root hole</td> </tr> </tbody> </table>	DIA	TYPE	BEARS	DIST	FACE/MARKINGS	17"	Hemlock Sn.	N 71°45' W	11.5 FT	10 FT tall Snag, Healed Double Blaze	10"	Hemlock W.	S 85° E<R>	4.3 FT<R>	Windfall, laying on face, large root hole
DIA	TYPE	BEARS	DIST	FACE/MARKINGS												
17"	Hemlock Sn.	N 71°45' W	11.5 FT	10 FT tall Snag, Healed Double Blaze												
10"	Hemlock W.	S 85° E<R>	4.3 FT<R>	Windfall, laying on face, large root hole												
<p>PLANE COORDINATE POSITION DATA</p> <p>State <u>OR</u> Zone <u>UTM-10M</u></p> <p>North <u>4990352</u></p> <p>East <u>431948</u></p> <p>Estab. By <u>GCDB</u></p>	<p>DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER</p> <p>Access from PVT land through clearcut and cat roads to the NE corner of clearcut, requires gate key. Access from USFS take forest road 12 to turnout .5 miles east of 127 spur, walk south towards clearcut, avoid creek to east once arrive at clearcut walk east to corner on timber edge.</p>															

Signature	Title <u>LSIT</u>	Division <u>LANDS</u>	Headquarters <u>SPRINGFIELD</u>	Date <u>12/2010</u>	7100-52 (3/68)
-----------	-------------------	-----------------------	---------------------------------	---------------------	----------------

CORNER RECORD (PERPETUATION)

<p>MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT</p> <p>Reset found monument in proportioned position on section line T6S R10W Added "LS2561""2010" stamp to cap, cap now reads S1/16 S11 S12 LS 2561 LS 1102 2010 1988</p>	<p>REGISTERED PROFESSIONAL LAND SURVEYOR</p> <p><i>John Ransom</i></p> <p>OREGON JULY 21, 1992 JOHN C. RANSOM 2561</p>
---	---

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Painted 6" Band around BT's and painted face blazes, new nails on signs, cleared brush around corner marked new trees

17"	Hemlock	BRS	N 52°30'W	112.4 FT	Scribed "S1/16 S11""BT" on double blaze
13"	Hemlock	BRS	S 52° E	24.9 FT	Scribed "S1/16 S12""BT" on double blaze

New trees include 3/4" brass washer mkd "LS2561" nailed to face between B & T on lower blaze

DONE BY: Jonathan Drew TITLE LSIT DATE 12/2010 PLS NO./AGENCY/STATE USDA Forest Service

Certified Cor. Record Prepared ? _____ Filed At: _____ DATE _____

REMARKS

Carsonite Post 2 FT South and West

New Bearing Trees measured with Leica 1200 total station and edm, basis of bearing is CSF# B-1330 or N 01°46'26"E between section corner to south and 1/4 to north

Index File No H-21 T. 6S R. 10W M. W.M. Proj No. Panther Cor. Siuslaw /16

