

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 21 and 28	TOWNSHIP 1 South	RANGE 10 West
COUNTY: Tillamook		DATE: 6-02-11
CORNER DESIGNATION: The Quarter Corner common to Sections 21 and 28, T. 1 S., R. 10 W., W.M.		(Please check one)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset at surface
<input type="checkbox"/> Referenced Out		
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0337 Page 279, GLO 1S10 Pages 78 - 79 (1890), Tillamook County Survey Records.		
Found Monument(s) and Accessories (Condition & Source): Found a 2 1/2" Brass Cap on a 3/4" Iron Pipe inside of a 1 1/2" Iron Pipe, not of record, in good condition. The monument is stamped as shown hereon. Double occupied the monument using GPS established control. The Oregon North Zone State Plane in NAD 83/91 grid coordinate position for the monument is N = 673684.899, E = 7325681.478, U.S. Feet. Lat: N = 45°27'49.306255" Long: W = 123°55'00.94358". Found a white painted cedar post lying down next to monument. (G.L.O.) – Found rotten remains of the (30" diameter Hemlock bearing S 8° W 12 lks. [7.92']). (G.L.O.) – Found rotten remains of the (40" diameter Hemlock bearing N 40° W 9 lks. [5.94']). () Indicates record information from Tillamook County Survey Records. [] Indicates calculated record distance from links to feet.		
Sketch of Monument Found:	Sketch of Re-Set Monument:	
New accessories set: Found monument was referenced out and a new monument was set. Set 120 lbs. of concrete in a 12" diameter cylinder around monument. Set a 72" hat section post with a yellow metal location tag 3.0' South of monument.		
New Bearing Trees set: No suitable Bearing Trees in the area.		
Location & Comments: Corner is located in a clear cut approximately 200' westerly of the satellite tower road.		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor		<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> REGISTERED PROFESSIONAL LAND SURVEYOR </div>
Notes: Digital images were taken of the new monument and its accessories.		
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor. Michael R. Rice, L.S.I. 16723, Survey Technician		<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067 </div>
		RENEWAL DATE: 08-30-2013



BOOK 7 609