OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT **Tillamook County Surveyor's Office**

SECTION: South one-quarter corner Section 34	TOWNSHIP 3 South, 4 South	RANGE 10 West		
COUNTY: Tillamook			DATE: 05-07-12	
CORNER DESIGNATION: Section corner common to Sections 34 and 3, (Please check one)				
Township 3 South, Range 10 West, Township 4 South, Range 10 West				Condition Report Only
W.M.				GPS Session
			×	Rewitness
				Unrecorded
				Surveyed In
				Referenced Out
Province Positionana Postantiana and Surveys at a Positiona Corr				
Previous Rewitnesses, Restorations and Surveys, etc.: Rewitness Card #645; Rewitness Book 2, Page 261; Rewitness Book 3, Page 368 A and B; Map B-1141; Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Brass cap, up 1.0' from ground and located in a North-South running tree line. Monument is in good condition. Set 120 pounds of concrete and a 12" plastic cylinder around the monument. Found a steel post with metal tag South 7.0'. Found orange carsonite posts located South 3.0' and North 2.0'. 1983 Map B-1141-12" Alder S70°W 36.7' with "650 T4S S3 1/4BT" scribed in bark. Now it is a shell of a 12" diameter by 2.0' tall stump with metal tags attached located at record position. 1983 Map B-1141-34" Spruce N82°W 86.5' with healed face. Now it is a 58" diameter Spruce tree found at record position. 1983 Map B-1141- Found a reference monument that was set on Map B-1141 at record position (N13-16E 48.1'). The brass cap is stamped as shown on sheet 6 of 6 for Map B-1141, Tillamook County Survey Records. GPS observations have been obtained for this corner position by setting GPS control and conventionally tying the corner monument from said control. The coordinates are provided here in WGS84, Latitude and Longitude. Latitude: North 45° 15' 34.13625"; Longitude: West 123° 53' 41.11850".				
Sketch of Found Monument:			Sketch of Set Monument: N/A	
7 3 S R 10 W 34 34 3 7 4 S 1970				
New accessories set: Set a 72" hat section post West 2.0'				
New Bearing Trees: An 18" Spruce scribed "T3SR10WS34BT" which bears North 46° West 16.7'; A 19" diameter by 1.0'				
tall Douglas Fir stump with tag and a nail in the center of the stump which bears South 72° East 25.5'.				
	corner monument is located approxir			
Firm / Agency:				SURVEYOR'S SEAL
Address: TILLAMOOK COUN	TY SURVEYOR'S OFFICE		•	

201 Laurel Avenue

Tillamook, Oregon 97141

Party Chief: Joe Jensen, P.L.S. 60067, Deputy County

Surveyor and Survey Supervisor.

Notes: Digital images have been taken of the monument,

reference monument and monument accessories.

Witness: Danny R. McNutt, P.L.S. 49230, Tillamook County

Surveyor, Michael R. Rice, L.S.I. 16723, Survey Technician.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON/ JANUARY 10, 2008 JOSEPH V. JENSEN

60067

RENEWAL DATE: 08-30- 2013

