

USDA-FOREST SERVICE

Index

CORNER RECORD (SEARCH)

File No. Z-20 PROJ. NO. Horn CORNER E1/16
TOWNS. 3S. & 4S. RANGE 10 W. R.D. Hebo COUNTY Tillamook GCDB# 560100
MERID. W.M. FOREST SIU STATE Oregon

CORNER DIAGRAM: Circle with S35, S2, 1971, OLS 816. DESCRIBE CORNER MONUMENT FOUND: Found 2-3/4" Brass Cap on 2-1/2" Iron Pipe, Projecting 1" above ground. DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND: Table with columns DIA, TYPE, BEARS, DIST, FACE/MARKINGS. PHOTO IDENTIFICATION DATA: Photo No., Filed At., Obj. Ident., Ident. By, Signature. PLANE COORDINATE POSITION DATA: State, Zone, North, West, Etab. By.

Signature Title Division Headquarters Date 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT. Cleared brush around corner, painted bearing trees, replace/maintained signs. Maintained Line West ~3/8 Mile & North 1/4 Mile, Blazed and Posted to standard. REGISTERED PROFESSIONAL LAND SURVEYOR: John Ransom, OREGON JULY 21, 1992 JOHN C. RANSOM 2561

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE. Marked 9" Alder Bears S 17° E - 1.9 FT MKD "E1/16 S2""BT" on Double Blaze with 3/4" Brass Washer"LS2561" On lower blz 6" Fir Bears N 55° E - 5.5 FT MKD "E1/16 S35""BT" on Double Blaze with 3/4" Brass Washer"LS2561" On lower bl

DONE BY: Jonathan Drew TITLE LSIT DATE FY 2012 PLS NO./AGENCY/STATE Certified Cor. Record Prepared? Yes Filed At: TILLAMOOK COUNTY DATE

REMARKS MEASUREMENTS TO ACCESSORIES MADE WITH STAFF COMPASS(15-1/2° DEC) AND STEEL TAPE

Index File No Z-20 T. 3S. & 4S. R. 10 W. Merid. W.M. Cor. E1/16

