


USDA-FOREST SERVICE

Index

CORNER RECORD (SEARCH)

File No. B-15 PROJ. NO. Horn CORNER CN 1/16
 TOWNS. 4 S. RANGE 10 W. R.D. Hebo COUNTY Tillamook GCDB# 440660
 MERID. W.M. FOREST SIU STATE Oregon

<p>CORNER DIAGRAM</p> 	<p>DESCRIBE CORNER MONUMENT FOUND Found 3-1/4" Aluminum Cap on 2-1/2" Aluminum Pipe Projecting 1" Above Ground</p>															
<p>PHOTO IDENTIFICATION DATA Photo No. _____ Filed At. _____ Obj. Ident. _____ Ident. By _____ Signature _____</p>	<p>DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND</p> <table border="1"> <thead> <tr> <th>DIA</th> <th>TYPE</th> <th>BEARS</th> <th>DIST</th> <th>FACE/MARKINGS</th> </tr> </thead> <tbody> <tr> <td>INDT</td> <td>Alder</td> <td>(S 57° E)</td> <td>(15.9')</td> <td>Rotting Remains Found No Root Hole</td> </tr> <tr> <td>3.25"</td> <td>Al. Cap RM</td> <td>N 6° E</td> <td>49.6'</td> <td>Found Standard 3-1/4" Aluminum cap Projecting 10" Above Ground marked as shown</td> </tr> </tbody> </table> <p style="text-align: right;">() = Record 1983</p>	DIA	TYPE	BEARS	DIST	FACE/MARKINGS	INDT	Alder	(S 57° E)	(15.9')	Rotting Remains Found No Root Hole	3.25"	Al. Cap RM	N 6° E	49.6'	Found Standard 3-1/4" Aluminum cap Projecting 10" Above Ground marked as shown
DIA	TYPE	BEARS	DIST	FACE/MARKINGS												
INDT	Alder	(S 57° E)	(15.9')	Rotting Remains Found No Root Hole												
3.25"	Al. Cap RM	N 6° E	49.6'	Found Standard 3-1/4" Aluminum cap Projecting 10" Above Ground marked as shown												
<p>PLANE COORDINATE POSITION DATA State _____ Zone _____ North _____ West _____ Estab. By _____</p>	<p>DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER Corner is 60' South of Private Timberline on a South Slope North of the creek about 200 feet, Follow Farmer Creek Road to private spur just south of Section Line 34/3, Follow road to west timber edge, follow edge South 250' to corner</p>															

Signature _____ Title _____ Division _____ Headquarters _____ Date 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

<p>MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT</p> <p>Cleared brush around corner, painted bearing trees, replace/maintained signs Maintained Line East .5 Miles, Blazed and Posted to standard</p>	<div style="border: 1px solid black; padding: 5px;"> <p style="text-align: center;">REGISTERED PROFESSIONAL LAND SURVEYOR</p> <p style="text-align: center;"><i>John Ransom</i></p> <p style="text-align: center;">OREGON JULY 21, 1992 JOHN C. RANSOM 2561</p> </div>
<p>ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE</p> <p>Marked 12" Spruce Bears S 69° E 55.7' Scribed "CN1/16S3""BT" on Double Blaze with 3/4" Brass Washer "LS2561"</p>	
<p>DONE BY: <u>Jonathan Drew</u> TITLE <u>LSIT</u> DATE <u>FY 2012</u> PLS NO./AGENCY/STATE _____ Certified Cor. Record Prepared? <u>Yes</u> Filed At: <u>TILLAMOOK COUNTY</u> DATE _____</p>	
<p style="text-align: center;">REMARKS</p> <p>MEASUREMENTS TO ACCESSORIES MADE WITH STAFF COMPASS(15-1/2° DEC) AND STEEL TAPE</p>	

Index File No B-15 T. 4 S. R. 10 W. M. W.M. Proj No. Horn Cor. CN 1/16

