


OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT  
Tillamook County Surveyor's Office

<b>SECTION:</b> 33	<b>TOWNSHIP:</b> 1N	<b>RANGE:</b> 9W
<b>COUNTY:</b> TILLAMOOK		<b>DATE:</b> SEPT. 18, 2015
<b>CORNER DESIGNATION:</b> C-E 1/16		<b>(Please Check One)</b>
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Not Found
		<input type="checkbox"/> Reset
		<input type="checkbox"/> Referenced Out
<b>Previous Rewitnesses, Restorations, Surveys, etc.:</b> MAP B-663		
<b>Found Monument(s) and Accessories(Condition &amp; Source):</b> FOUND OREGON STATE BOARD OF FORESTRY BRASS CAP ON GALVANIZED IRON PIPE STAMPED "E 1/16 C-C S33 1972", 0.1' BELOW GRADE, FROM WHICH: 50" HEMLOCK WITH HEALED FACE BEARS (N31 1/2 'W 74.5'); (10' HEMLOCK BEARS S6°E 16') NOW GONE.		
<b>Monument Set(Procedures &amp; Description):</b>		
<b>Other New Accessories Set:</b> STEEL FENCE POST NORTH 1.0'; 5/8"X40" REBAR WITH PLASTIC CAP MARKED "TERRYJONES LS 2507" BEARS S29°24'51"W 185.84'		
<b>New Bearing Trees:</b>		
<b>Location &amp; Comments:</b> MONUMENT IS EAST ±20' FROM CENTERLINE OF KILCHIS FOREST ROAD.	<b>Surveyor's Stamp</b>  renewal date 6-30-17	
<b>Firm/Agency:</b> BAYSIDE SURVEYING		
<b>Address:</b> 11765 HWY 101 SOUTH TILLAMOOK, OR 97141		
<b>Party Chief:</b> TERRY JONES		
<b>Notes:</b> FILE NAME rewitness\TIS-R9W-S33-CE1-16.xls		Office Use Only
<b>Witness(es):</b> TLJ/DWE/TCH		

