




OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 9	TOWNSHIP: 3S	RANGE: 8W
COUNTY: TILLAMOOK		DATE: JUNE 20, 2016
CORNER DESIGNATION: N 1/16 CORNER ON EAST LINE SEC 9 NORTH 1/16 CORNER COMMON TO SECTIONS 9 & 10, T3S, R8W.		(Please Check One)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Not Found
		<input type="checkbox"/> Reset
<input type="checkbox"/> Referenced Out		
Previous Rewitnesses, Restorations, Surveys, etc.: 		
Found Monument(s) and Accessories(Condition & Source): FOUND OREGON STATE BOARD OF FORESTRY BRASS CAP ON 1 1/2" GALVANIZED IRON PIPE STAMPED "N 1/16 S9 S10 1964 RS 401", SOLID IN GROUND BUT ABOUT 12" OF PIPE IS EXPOSED, FROM WHICH: NORTHEAST BEARING TREE GONE (29" FIR N26°E 37.0'); 22" (18") FIR STUMP WITH HEALED FACE, BEARS (S 56° W 73.8'), SEE MAP A-1158.		
Monument Set(Procedures & Description):		
Other New Accessories Set: SET CARSONITE POST 1' NORTH;		
New Bearing Trees: 16" SPRUCE SCRIBED "N1/16 S10 BT" BEARS N 79° E 19.12' TO BRASS NAIL AND WASHER; 8" DOUG FIR SCRIBED "N1/16 S9 BT", BEARS N 21° W14.96' TO BRASS NAIL & WASHER. THE BRASS NAILS AND WASHERS ARE SCRIBED "LS 2507" AND BETWEEN THE B & T.		
Location & Comments: MONUMENT IS LOCATED ON STEEP NORTH SLOPE.		Surveyor's Stamp  RENEWAL DATE 6-30-17
Firm/Agency: BAYSIDE SURVEYING		
Address: 11765 HWY 101 SOUTH TILLAMOOK, OR 97141		
Party Chief: TERRY JONES		
Notes: FILE NAME rewitness\T3S-R8W-S9-EASTLINE-N1-16.xls		Office Use Only 
Witness(es): TLJ/DWE		