

**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
Tillamook County Surveyor's Office

<b>SECTION:</b> Northwest corner Section 29	<b>TOWNSHIP</b> 1 South	<b>RANGE</b> 10 West
---	-------------------------	----------------------

<b>COUNTY:</b> Tillamook	<b>DATE:</b> 09-01-14
--------------------------	-----------------------

Rewitness of a found 1" diameter iron pipe at The Northwest corner of Section 29, Township 1 South, Range 10 West; W.M., Tillamook County, Oregon.	(Please check one) <table border="1" style="width:100%; border-collapse: collapse;"> <tr><td><input type="checkbox"/></td><td>Condition Report Only</td></tr> <tr><td><input type="checkbox"/></td><td>Restoration</td></tr> <tr><td><input checked="" type="checkbox"/></td><td>Rewitness</td></tr> <tr><td><input type="checkbox"/></td><td>Unrecorded</td></tr> <tr><td><input checked="" type="checkbox"/></td><td>Brass Cap set at surface</td></tr> <tr><td><input type="checkbox"/></td><td>Referenced Out</td></tr> </table>	<input type="checkbox"/>	Condition Report Only	<input type="checkbox"/>	Restoration	<input checked="" type="checkbox"/>	Rewitness	<input type="checkbox"/>	Unrecorded	<input checked="" type="checkbox"/>	Brass Cap set at surface	<input type="checkbox"/>	Referenced Out
<input type="checkbox"/>	Condition Report Only												
<input type="checkbox"/>	Restoration												
<input checked="" type="checkbox"/>	Rewitness												
<input type="checkbox"/>	Unrecorded												
<input checked="" type="checkbox"/>	Brass Cap set at surface												
<input type="checkbox"/>	Referenced Out												

**Previous Rewitnesses, Restorations and Surveys, etc:** See BLM Field Notes Volume: OR-R0053 pages 211 and 212 for G.L.O. original notes (1857); See Note 3 on Survey map B-819 (1978), Tillamook County Survey Records, for the Crown Zellerbach Corporation history of section corner monumentation.

**Found Monument(s) and Accessories (Condition & Source):** Found a 1" diameter iron pipe at corner location. Set 2" diameter iron pipe and a 3" diameter Tillamook County Brass cap stamped as shown hereon over the 1" diameter iron pipe. Set the pipe and brass disk in 120 pounds of concrete inside a 12" diameter plastic pipe. Found a rotten wood post with a location tag lying at the found 1" diameter iron pipe. Found an iron fence post with a yellow metal location tag 0.6' North. Found a 6' tall x a 26" diameter Hemlock stub with axe marks at record bearing and distance of North 84° West a distance of 10.9'.

Conventionally tied the monument using two GPS established control points. The Oregon North Zone State Plane in NAD 83/91 grid coordinate for the position is N = 674098.777, E = 7317767.659 U.S. Survey Feet.

The coordinates have been converted and are also provided here in WGS 84, Latitude and Longitude.  
North = 45°27'50.07039", West= 123°56'52.13338"

<p><b>Monument Set (Procedures and Description):</b> Set a 3" diameter Tillamook County brass cap and a 2-1/2" diameter iron pipe over the found 1" iron pipe. The monument was set in 120 pounds of concrete inside a 12" diameter plastic container. The brass cap is stamped as shown hereon.</p>	<p><b>Sketch of Found Monument:</b></p> <div style="text-align: center;"> </div>
--	--

**New accessories set:** See below.

**New Bearing Trees set:** A 10" diameter Sitka Spruce scribed "T1SR10WS29BT" with yellow metal location tags, also with a nail and yellow Tillamook County washer set between the 'B&T" which bears South 89° East 7.7'.  
An 11" diameter Sitka Spruce scribed "T1SR10WS20BT" with yellow metal location tags, also with a nail and yellow Tillamook County washer set between the 'B&T" which bears North 27° East 32.0'.  
A 21" diameter Hemlock scribed "T1SR10WS19BT" with yellow metal location tags, also with a nail and yellow Tillamook County washer set between the 'B&T" which bears North 73° West 17.6'.

**Location & Comments:** This corner is located approximately 400 feet in a Northwesterly direction along logging roads #618A and #618.

<b>Firm / Agency</b> Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141
<b>Party Chief:</b> Joe Jensen, PLS 60067, Survey Supervisor
<b>Notes:</b>
<b>Witnesses:</b> Danny R. McNutt, PLS 49230, Tillamook County Surveyor. Michael R. Rice, P.L.S. 86926, Survey Technician

**SURVEYOR'S SEAL**

**REGISTERED PROFESSIONAL LAND SURVEYOR**

*Joseph V. Jensen*

OREGON  
 JANUARY 10, 2008  
**JOSEPH V. JENSEN**  
 60067

RENEWAL DATE: 03-30-15

