## OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT Tillamook County Surveyor's Office

SECTION:	2	TOWNSHIP:	38	RANGE:	W8
COUNTY:		TILLAMOOK			<b>DATE:</b> JUNE 20, 2016
CORNER DESIGN					(Please Check One)
SOUTHEAST 1/16	CORNER O	F SECTION 2, T3S, R8	W.		Condition Report Only
					Restoration
					X Rewitness
					Not Found
					Reset Referenced Out
Provious Powits	eene Danta	rations Survoyo ata			Referenced Out
		rations, Surveys, etc.: JNTY SURVEY RECOR			
FOUND OREGON GALVANIZED IRC WITH HEALED FA	I STATE BOA ON PIPE LEAI ACE AND YEI	NING SOUTH, ON SOU	RASS CAP STA TH EDGE OF ON POSTER E	OLD CAT ROA	16 S2 1973 RS 707" ON 1 1/2" AD, FROM WHICH: 38" (23") FIR '2° W 23.9'); 36" (16") CEDAR WITH
Monument Set(P	rocedures &	Description):			
		SET AT RECORD DISTINEW DIAMETER OF E			SE1/16 S2 1973 RS 707
Other New Acces	sories Set				
CARSONITE POS	A STATE OF THE PARTY OF THE PAR	1			
New Bearing Tre	es:				
Location & Com	ments:		- 11 3 3 3 3	Surveyor's S	Stamp
	ON SOUTH EIGLEAR-CUT.  YING SOUTH	OGE OF OLD CAT ROA	ND, SOUTH	PROFILAND S	ISTERED ESSIONAL CUPVEYOR
Notes: FILE NAME rewiti	ness\T3S-R8\	V-S2-SE1-16.xls		Office Use Only	COK CON
Witness(es): TLJ/DWE				J Ganu	DATE (3) ary 27,2017
				TO THE	GRS OFF